16505A-01 16505A Prototype Analyzer Serial Numbers: 0000A00000 / 9999Z99999 Y2K update information. Product requires Software update revision 1.40 To Be Performed By: HP-Qualified Personnel, and customer Parts Required: HP P/N Description Quanty 16505-68714 SW Update CD-ROM v1.40 Situation: The HP 16505A Prototype Analyzer User Registration password will yield an "invalid" status after 31 Dec 1999 even though a valid password is entered. Consequently the User Registration window will always appear after the instruments boots. Otherwise the HP 16505A will operate as expected after 31 Dec 1999, including all visible date-related functions. Solution / Action: Install operating system software revision 1.40 using the procedure provided with the update CD-ROM. Operating system software version 1.40 disables the User Registration utility because HP is not planning any more software revisions for the HP 16505A product. A SCSI CD-ROM drive is required to install the update. Revision v1.40 is planned to release on 01 Dec 1998 and will be automatically sent to all currently registered HP 16505A users. Date: 02 Nov 1998 * MODIFICATION RECOMMENDED _____ * STANDARDS: LABOR HOURS _0.5 * ACTION CATEGORY: ON SPECIFIED FAILURE ____ IMMEDIATELY ___ * * AGREEABLE TIME XX LOCATION CATEGORY: CUSTOMER INSTALLABLE XX ON-SITE XX * * HP LOCATION XX AVAILABILITY: PRODUCT'S SUPPORT LIFE SERVICE INVENTORY: RETURN _____ SCRAP ____ SEE TEXT * USED PARTS: RETURN _ SCRAP ____ SEE TEXT * * HP RESPONSIBLE UNTIL:_02 Nov 2000_ * AUTHOR/ENTITY: _RB/0800__ * ADDITIONAL INFO:

HP has made every effort to ensure the accuracy of our product testing. However, because each customer's environment is different from HP's laboratory test environment, it is the customer's responsibility to validate the Year 2000 readiness of these products in their own environment. Therefore, information about the Year 2000 status of HP products is provided "as is" without warranties of any kind and is subject to change without notice. HP makes no representation or warranty respecting the accuracy or reliability of information about non-HP products. Such information, if any, was provided by the manufacturers of those products and customers are urged to contact the manufacturer directly to verify Year 2000 readiness. The information provided here constitutes a Year 2000 Readiness Disclosure for purposes of the Year 2000 Information and Readiness Disclosure Act.