

S E R V I C E N O T E

SUPERSEDES: None

**Logic Analyzer**

**Serial Numbers:** US00000/US99999

**Duplicate Service Notes:** 1660A-03 1660AS-03  
 1661A-03 1661AS-03  
 1662A-03 1662AS-03  
 1663A-03 1663AS-03

**Cables can be purchased by Agilent Personnel or customers.**

**Situation:**

The two cables, 16555-61606 and 01660-61605, are not going to be available to meet the end of support date for the models mentioned above.

**Solution / Action:**

The two cables are being replaced by the part number 16710-61603. Mixed cable numbers cannot be used together. The 16710 has a different propagation delay and will not work with any other cables besides itself. This cable must be ordered through kit numbers. The kit numbers are:

- 01660-60007: Consists of four 16710-61603 cables.
- 01661-60001: Consists of three 16710-61603 cables.
- 01662-60001: Consists of two 16710-61603 cables.
- 16710-61603: Consists of one 16710-61603 cable.

DATE: November 2001

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
<b>INFORMATION ONLY</b>		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
AR	0800	

