

S E R V I C E N O T E

SUPERSEDES: None

Logic Analyzer

Serial Numbers: US00000/US99999

Duplicate Service Notes:	1660C-02	1660CS-02	1660CP-01
	1661C-02	1661CS-02	1661CP-01
	1662C-02	1662CS-02	1662CP-01
	1663C-02	1663CS-02	1663CP-01

Cables can be purchased by Agilent Personnel or customers.

Situation:

The two cables, 16555-61606 and 01660-61605, are not going to be available to meet the end of support date for the models mentioned above.

Solution / Action:

The two cables are being replaced by the part number 16710-61603. Mixed cable numbers cannot be used together. The 16710 has a different propagation delay and will not work with any other cables besides itself. This cable must be ordered through kit numbers. The kit numbers are:

- 01660-60007: Consists of four 16710-61603 cables.
- 01661-60001: Consists of three 16710-61603 cables.
- 01662-60001: Consists of two 16710-61603 cables.
- 16710-61603: Consists of one 16710-61603 cable.

DATE: November 2001

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
AR	0800	

