

S E R V I C E N O T E

SUPERSEDES: None

Logic Analyzer**Serial Numbers:** US00000/US99999**Duplicate Service Notes:**

1661E-02	1662E-02
1663E-02	1660ES-02
1661ES-02	1662ES-02
1663ES-02	1660EP-02
1661EP-02	1662EP-02
1663EP-02	1660E-02

Cables can be purchased by Agilent Personnel or customers.**Situation:**

The two cables, 16555-61606 and 01660-61605, are not going to be available to meet the end of support date for the models mentioned above.

Solution / Action:

The two cables are being replaced by the part number 16710-61603. Mixed cable numbers cannot be used together. The 16710 has a different propagation delay and will not work with any other cables besides itself. This cable must be ordered through kit numbers. The kit numbers are:

01660-60007: Consists of four 16710-61603 cables.
 01661-60001: Consists of three 16710-61603 cables.
 01662-60001: Consists of two 16710-61603 cables.
 16710-61603: Consists of one 16710-61603 cable.

DATE: November 2001

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

AR

ENTITY:

0800

ADDITIONAL INFORMATION:

