

S E R V I C E N O T E

SUPERSEDES: None

16008B Resistivity Cell

Serial Numbers: 3212J00216 / 3212J00251

Duplicate Service Notes: None

Replacement of the main electrode

To Be Performed By: Agilent-Qualified Personnel or Customer

Parts Required:

Part No.	Qty.	Description
16008-60081	1	50mm Main Electrode
16008-60083	1	26mm Main Electrode (Option 001/002)
16008-60085	1	76mm Main Electrode (Option 001/003)

Situation:

The 16008B's main electrode (P/N 16008-60081/60083/60085) has the conductive elastomer sheet adhered on it. In above serialized units, the conductive elastomer sheet may not have been adhered tightly.

Solution/Action:

If the elastomer sheet peels off, replace the entire defective main electrode with a new one which has the elastomer sheet on it.

DATE: 31 May 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
MODIFICATION RECOMMENDED					
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor hrs		
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: 31 May 1996		
AUTHOR: YM	ENTITY: 3355	ADDITIONAL INFORMATION:			