

S E R V I C E N O T E

SUPERSEDES: None

16117B Low-Noise Test Leads**Recommended Replacement Parts****To Be Performed By:** Customer Replaceable**Parts Required:** None**Situation:**

16117B is a low noise test lead for 4339A. 16117B's triaxial/BNC cable assemblies (P/N 16117-61601/61602) consists of a black cover (P/N 16117-25002), a gold contact plug (P/N 1252-4583), and the rest of the assemblies as shown in chapter 4 of Operation and Service Manual (P/N 16117-90010).

The black cover is attached to the cable assembly with a screw. If the black cover is not attached tightly, the wire soldered to the gold contact plug may be broken. The cover is tightened when shipped from the factory, but sometimes customers may loosen the black cover and the wire may be damaged.

Solution/Action:

To avoid this trouble, the black cover has been adhered to the cable assembly when shipped from the factory. So the black cover and the gold contact plug are not replaceable in this new type cable assembly. Also, when the black cover or the gold contact plug of the old type assembly are damaged, replace the whole triaxial/BNC cable assembly (P/N 16117-61601/61602) to avoid the trouble.

DATE: October 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

ENTITY:

ADDITIONAL INFORMATION:

YM

3355