

S E R V I C E N O T E

SUPERSEDES: None

16117D Low Noise Test Leads

Serial Numbers: 0000J00000 / 9999J99999

Information On Replacing Parts

Duplicate Service Notes: None

To Be Performed By: Agilent-Qualified Personnel

Parts Required:

Part No.	Qty.	Description
04142-61641	1	Cable Assembly (1 M) #1
1250-1906	1	Triaxial Adapter Female

#1 If the cable length is not 1m, use the following part numbers:

Part No.	Qty.	Description
04142-61631	1	Cable Assembly (0.5 M)
04142-61632	1	Cable Assembly (1.5 M)
04142-61633	1	Cable Assembly (2 M)

Continued

DATE: 01 November 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
MT	3301	

Situation:

There is no Operation and Service Manual for the 16117D.

Solution/Action:

Refer to the above list when replacing parts of the 16117D. The “Cable Assembly” means a triaxial cable with a male triaxial connector at both ends of the cable.