

S E R V I C E N O T E

SUPERSEDES: None

8447F Amplifier**Serial Numbers:** 0000A00000 / 2805A03498**Duplicate Service Notes:** 8447A-09, 8447D-09, 8447E-09**Power switch replacement kits****Parts Required:**

08447-60060 / 8447F Standard

08447-60061 / 8447F Option 010

08447-60062 / 8447F Option H64

Situation:

Earlier power switches, S1, have been discontinued by the manufacturer. Kits are required to replace the old switches with a newer style because a different front panel is required.

Solution/Action:

Order the switch replacement kits when replacing S1 in instruments with the serial numbers described.

DATE: January 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

GPB

ENTITY:

5320

ADDITIONAL INFORMATION: