

S E R V I C E N O T E

SUPERSEDES: 70600A-02A

70300A Tracking Generator, Option 001
70600A Preselector
70601A Preselector
70904A RF Section
70905A RF Section
70906A RF Section
70907A External Mixer Interface

Serial Numbers: See Table of Affected Serial Numbers

Replacement for Obsolete Attenuators

Applicable Installation Note: 5958-7185

Duplicate Service Notes:

70300A-07B
 70600A-02B
 70601A-02B
 70904A-05B
 70905A-05B
 70906A-05B
 70907A-03B

Continued

DATE: 04 February 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

<p>AUTHOR: SR</p>	<p>ENTITY: 5300</p>	<p>ADDITIONAL INFORMATION:</p>
-----------------------	-------------------------	--------------------------------

Table of Affected Serial Numbers	
70300A	0000A00000 / 2818A00542
70600A	0000A00000 / 2930A00465
70601A	0000A00000 / 2929A00146
70904A	0000A00000 / 2924A01254
70905A	0000A00000 / 2925A00776
70906A	0000A00000 / 2928A00406
70907A	0000A00000 / 2932A00370

Situation:

The attenuators for the instruments within the serial numbers listed above are obsolete. When a failure occurs they should be replaced.

For ordering convenience, the parts required to make this change are available in a retrofit kit. Refer to Table 1 for proper Retrofit Kit part numbers for your instrument.

Table 1. Retrofit Kit Ordering Information

For Instrument	Order: Retrofit Kit Part No.	Kit Includes: New Attenuator Part No.	Replaces Old Attenuator Part No.
70300A Option 001	5062-6410	5086-7844	5086-7753
70600A	5062-6418	5086-7842	5086-7365
70601A	5062-6420	5086-7837	5086-7763
70904A	5062-6419	5086-7843	5086-7724
70905A	5062-6420	5086-7837	5086-7365
70906A	5062-6420	5086-7837	5086-7763
70907A	5062-6410	5086-7844	5086-7753