

INFORMATION ONLY – DOES NOT COMMUNICATE  
A MODIFICATION OR SAFETY CONDITION

**8753D-07**

# S E R V I C E N O T E

Supersedes:  
None

## 8753D Vector Network Analyzer

Serial Numbers: [0000A00000 / 9999Z99999]

**Option 75 ohm System verification test is missing from the 8753D manual.**

**Parts Required:**

P/N	Description	Qty.
08753-90484	8753ES Manual	1
11852B	Minimum-Loss Pad 50 ohm to 75 ohm	2
11525A	Adapter APC-7 to Type-N Male	2

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR: [initials]      PRODUCT LINE: WN

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002  
PRINTED IN U.S.A.



August 14, 2002

**Situation:**

System verification test is missing from the 8753D manual for the Network Analyzers with option 075 (75 Ohm test set).

**Solution/Action:**

For Option 075 system verification use the 8753ES Service Guide manual 08753-90484 chapter 2 procedure. System Verification can be performed by using minimum loss pads and Type N-7mm adapters.