# S E R V I C E N O T E

SUPERSEDES: None

## 8482H High-power sensor, 100 kHz to 4.2 GHz

### **Serial Numbers:**

3318A09291 / 3318A09393 MY41090101 / MY41090150 MY41090159 / MY41090168 MY41090203 / MY41090232 MY41090235 / MY41090237

### **ID Label (Maximum Power Limit) is incorrect**

To Be Performed By: Agilent-Qualified Personnel or Customer

#### Situation

The 08482-80001 8482H ID Label indicates a Maximum Power of 35 Watts.

### **Solution / Action:**

This label should indicate a Max. Pwr. of 3.5 Watts. For all 8482H sensors returned for calibration or repair and cal, Agilent Service Centers are to replace all labels stating 35 Watts free of charge. Corrected labels will be available on ePal on or before 1 July, 2001.

In addition, cal and repair will be performed free of charge for customers who indicate that their sensor was damaged by applying RF power levels based on the incorrect 35W maximum.

DATE: June 2001

### ADMINISTRATIVE INFORMATION

| INFORMATION ONLY |                  |                         |
|------------------|------------------|-------------------------|
|                  |                  |                         |
| AUTHOR:          | ENTITY:          | ADDITIONAL INFORMATION: |
| тс               | BEST PGU<br>5390 |                         |

© 2001 AGILENT TECHNOLOGIES PRINTED IN U.S.A.

