

Notice

Hewlett-Packard to Agilent Technologies Transition

This documentation supports a product that previously shipped under the Hewlett-Packard company brand name. The brand name has now been changed to Agilent Technologies. The two products are functionally identical, only our name has changed. The document still includes references to Hewlett-Packard products, some of which have been transitioned to Agilent Technologies.



Agilent Technologies

By internet, phone, or fax, get assistance with all your test and measurement needs.

Contacting Agilent

Online assistance: www.agilent.com/find/assist

United States
(tel) 1 800 452 4844

Latin America
(tel) (305) 269 7500
(fax) (305) 269 7599

Canada
(tel) 1 877 894 4414
(fax) (905) 282-6495

Europe
(tel) (+31) 20 547 2323
(fax) (+31) 20 547 2390

New Zealand
(tel) 0 800 738 378
(fax) (+64) 4 495 8950

Japan
(tel) (+81) 426 56 7832
(fax) (+81) 426 56 7840

Australia
(tel) 1 800 629 485
(fax) (+61) 3 9210 5947

Asia Call Center Numbers

Country	Phone Number	Fax Number
Singapore	1-800-375-8100	(65) 836-0252
Malaysia	1-800-828-848	1-800-801664
Philippines	(632) 8426802 1-800-16510170 (PLDT Subscriber Only)	(632) 8426809 1-800-16510288 (PLDT Subscriber Only)
Thailand	(088) 226-008 (outside Bangkok) (662) 661-3999 (within Bangkok)	(66) 1-661-3714
Hong Kong	800-930-871	(852) 2506 9233
Taiwan	0800-047-866	(886) 2 25456723
People's Republic of China	800-810-0189 (preferred) 10800-650-0021	10800-650-0121
India	1-600-11-2929	000-800-650-1101

PARTS SUPPLEMENT

New APC-7 Connector Coupling Nut


The new APC-7 coupling nut (HP Part Number 1250-1465) directly replaces the old APC-7 coupling nut (HP Part Number 1250-0819). The old and new coupling nuts are shown in the figure below.

The construction of the new coupling nut allows it to be torqued with a standard 3/4 inch open-end torque wrench for repeatable connections. The maximum torque to be applied to the coupling nut is 1.2 to 1.4 N·m (11 to 13 inch pounds). The new coupling nut mates with the old coupling nut. All other connector parts remain the same. Therefore, all performance characteristics are unchanged.

The table below lists the HP Part Numbers for the complete APC-7 connector with the new coupling nut; for the old and new coupling nuts; for the red plastic cap (dust and protective cover); for the tools required for disassembly, and for the complete APC-7 tool kit.

Description	HP Part Number
Connector, APC-7	1250-1466
Connector, Coupling Nut (New)	1250-1465
Connector, Coupling Nut (Old)	1250-0819
Cap, Protective	1401-0081

Description	HP Part Number
APC-7 Contact Extractor	5060-0236
APC-7 Spanner Wrench	5060-0237
Open-end Wrench	8710-0877
APC-7 Connector Tool Kit	11591A



New and Old Coupling Nuts for APC-7 Connectors

Customer Order Number

For Agilent Internal Reference Only
Manufacturing Part Number



5955-0657

Printed in USA

August 1977