

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

8665A-10A

S E R V I C E N O T E

Supersedes:
8665A-10

8665A Synthesized Signal Generator

Serial Numbers: 0000A00000 / 9999Z99999

New Power switch part number

Parts Required:

P/N	Description	Qty.
83750-60040	CABLE ASSEMBLY- FRONT SWITCH	1

Duplicate Service Notes:

8643A-05
8644A-06
8644B-06
8645A-07
8664A-09
8665B-08

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: MW/AKS

PRODUCT LINE: PL15

ADDITIONAL INFORMATION:

Recommended To Be Performed By: Agilent-Qualified Personnel

© AGILENT TECHNOLOGIES, INC. 2004
PRINTED IN U.S.A.



July 22, 2004

Situation:

The old part number (3101-2720) for the power switch on these instruments has been changed in production for one with increased reliability.

Solution/Action:

Order part number 83750-60040 instead.