

INFORMATION ONLY – DOES NOT COMMUNICATE  
A MODIFICATION OR SAFETY CONDITION

# E4438C-06A

## S E R V I C E N O T E

Supersedes:  
E4438C-06

E4438C

Serial Numbers: [0000A00000 / 9999Z99999]

**Mechanical attenuators, part number 33322-60014, with serial numbers less than 06400 (Made in USA) used in the identified products is susceptible to ozone-induced deterioration that results in erratic switching or stuck conditions.**

**Parts Required:**

P/N	Description	Qty.
33322-60014	Mechanical Attenuator	1

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

## INFORMATION ONLY

AUTHOR: Herb Upham    PRODUCT LINE: 15

ADDITIONAL INFORMATION:

Replacement of failing attenuators until 1AUG2006 if serial number is less than US 06400.

© AGILENT TECHNOLOGIES, INC. 2005  
PRINTED IN U.S.A.



July 18, 2005

**Situation:**

**Mechanical attenuators, part number 33332-60014, with serial numbers below 06400 (Made in USA) used in the identified products use rubber "O" rings that are susceptible to ozone-induced deterioration that results in erratic switching or stuck conditions. Attenuator serial numbers can be viewed by removing the outside instrument cover and inside top cover, the serial tag is on the front facing end of the attenuator.**

**Solution/Action:**

**Replace failed mechanical attenuators until 1AUG2006 under the authority of this Service Note.**