INFORMATION ONLY - DOES NOT COMMUNICATE A MODIFICATION OR SAFETY CONDITION

E8257D-09

S E R V I C E N O T E

Supersedes: None

E8257D Analog Signal Generator

Serial Numbers: [0000A00000 / 9999Z99999]

In an E8257D, when replacing a failed E8251-60046 A8 Output, replace it with the E8251-60339 A8 Output.

Parts Required:

P/N Description Qty.

E8251-60339 Output, Analog 1

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: DMc PRODUCT LINE: PL15

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2005 PRINTED IN U.S.A.



September 1, 2005

Page 2 of 2 E8257D-09

Situation:

The E8257D was released with an A8 Output board part number E8251-60046. A new, more reliable A8 Output board part number E8251-60339 has replaced the E8251-60046 in the E8257D. In E8257D only, any failed E8251-60046 should be replaced with the E8251-60339.

Solution/Action:

When replacing a failed E8251-60046 in an E8257D, it should be replaced with A8 Output board part number E8251-60339. If the firmware revision is not \geq C.04.17 it needs to be upgraded. The firmware and upgrade assistant information is available at

http://www.home.agilent.com/cgi-bin/pub/agilent/editorial/cp_MiscEditorial.jsp?NAV_ID=536891147.536881799.02&LANGUAGE_CODE=eng&CONTENT_KEY=1000000797%3aepsg%3asud&ID=1000000797%3aepsg%3asud&COUNTRY_CODE=US

The E8251-60339 is NOT backward compatible with older PSG analog models (E8241A/44A/51A/54A, E8247C/57C).