

INFORMATION ONLY – DOES NOT COMMUNICATE  
A MODIFICATION OR SAFETY CONDITION

**E8257D-14**

**S E R V I C E N O T E**

---

Supersedes:  
None

## E8257D Analog Signal Generator

Serial Numbers: [0000A00000 / 9999Z99999]

**This information only service note can be used by service center that want to carry an inventory of the most frequently replaced parts to reduce TAT.**

**Parts Required:**

<b>P/N</b>	<b>Description</b>	<b>Qty.</b>
E8251-60075	Output Board	
E8251-60328	FracN	
E8251-60048	Reference UNR	

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR: DMc    PRODUCT LINE: PL15

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2006  
PRINTED IN U.S.A.



**Agilent Technologies**

May 8, 2006

**Situation:**

To improve TAT service centers may want to order the following assemblies. These assemblies are the most frequently replaced parts in the E8257D as of May 2006. The number of parts to stock should be determined by each service center based on the specific service centers repair history for this model.

The inventory should be used at the first opportunity and replacement parts ordered and held for the next repair. This will keep the inventory current and up-to-date.

**Solution/Action:**

Recommended parts to stock:

Parts unique to the E8257D-

A8 Output Board part number E8251-60075 - The E8251-60075 replaces E8251-60046 and E8251-60339 part numbers in E8257D models only. The E8251-60075 requires firmware revision  $\geq$  C.04.53.

Parts common to E8257D and E8267D-

A6 FracN E8251-60328

A7 Reference UNR E8251-60048