

# E8257D-18

## S E R V I C E N O T E

Supersedes:  
NONE

### E8257D Analog Signal Generator

Serial Numbers: **MY00000000/MY46521040**  
**US00000000/US46461140**

**E8257D w/007 (Ramp sweep) found when sweeping between 1GHz and 2 GHz, the sweep frequency may appear to FM and then return to a swept signal.**

**Parts Required:**

P/N	Description	Qty.
NONE		

### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: <b>INFORMATION ONLY</b>
AUTHOR: Hong Hee, Ng      PRODUCT LINE: PL15
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2007  
PRINTED IN U.S.A.



September 14, 2007

**Situation:**

For the instrument with option 007, when performing the ramp sweep between 1GHz and 2GHz, the sweeping may appear to be FM signal at certain frequency.

**Solution/Action:**

1. Check the instruments firmware revision. Make sure the revision is C.04.71 or >C.04.92.
2. Connect the instrument to the LAN and write down the IP address.
3. Open a web browser on your pc. Enter the following URL, replacing <ip address> with the actual IP address of your instrument, <http://<ip address>/update>.
4. Type in or pastes the scripts to the manual update column then select EXECUTE. After the process has executed, there will be a message stating "Operation completed".

```
cd "FREQ SWEEP MULTIPLIER",3,8
cc "FREQ SWEEP MULTIPLIER"
cd "FREQ SWEEP MODULUS LATCH VALUE",3,9
cc "FREQ SWEEP MODULUS LATCH VALUE"
ky 43765
```