

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

E8267D-11

S E R V I C E N O T E

Supersedes:
None

E8267D Vector Signal Generator

Serial Numbers: [0000A00000 / 9999Z99999]

This information only service note can be used by service center that want to carry an inventory of the most frequently replaced parts to reduce TAT.

Parts Required:

| P/N | Description | Qty. |
|-------------|--------------------------|-------------|
| E8251-60339 | Output Board | |
| E4400-60671 | Baseband Generator Board | |
| E8251-60328 | FracN | |
| E8251-60048 | Reference UNR | |

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: DMc PRODUCT LINE: PL15

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2006
PRINTED IN U.S.A.



Agilent Technologies

May 8, 2006

Situation:

To improve TAT service centers may want to order the following assemblies. These assemblies are the most frequently replaced parts in the E8267D as of May 2006. The number of parts to stock should be determined by each service center based on the specific service centers repair history for this model.

The inventory should be used at the first opportunity and replacement parts ordered and held for the next repair. This will keep the inventory current and up-to-date.

Solution/Action:

Recommended parts to stock:

Parts unique to the E8267D-

A8 Output Board part number E8251-60339

A14 Baseband Generator Board part number E4400-60671. The E4400-60671 replaces the E4400-60744 and requires firmware \geq C.04.55.

Parts common to E8257D and E8267D-

A6 FracN E8251-60328

A7 Reference UNR E8251-60048