

S E R V I C E N O T E

SUPERSEDES: None

**HP 8560A Portable Spectrum Analyzer**

**Serial Numbers:** 0000A00000 / 9999A99999

**Duplicate Service Notes:**

- 8561A-26
- 8561B-15
- 8562A-57
- 8562B-55
- 8563A-08

**Log Fidelity Spec Corrections**

**To Be Performed By:** HP-Qualified Personnel or Customer

**Situation:**

Installation and Verification manuals for these spectrum analyzers contained information for testing and recording Incremental Log Fidelity in the Log Fidelity tests. This inclusion was an error.

In addition, earlier Installation and Verification manuals did not restrict the Log Fidelity in 10dB/Division to the top nine divisions of the display.

**Solution/Action:**

In the Log Fidelity test, ignore all references to Incremental Log Fidelity in the procedure, tables and test record. This applies to all log scales.

Add a note in Table 1-1 that the Log Fidelity in 10dB/Division applies only to the top nine divisions of the display.

DATE: 20 February 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
GPB	5300	