

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

8560EC-07

S E R V I C E N O T E

Supersedes:
None

8560EC Series Portable Spectrum Analyzers

Serial Numbers: 0000A00000 / 9999A99999

New A15 RF Board Replacement Part Numbers

Parts Required:

P/N	Description	Qty.
------------	--------------------	-------------

NOTE: No parts are required, as this is an Information Only service note.

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY
AUTHOR: MPM PRODUCT LINE: 12
ADDITIONAL INFORMATION: Replacement Part Number Update

© AGILENT TECHNOLOGIES, INC. 2004
PRINTED IN U.S.A.



December 20, 2004

Situation:

The instrument service guide does not correctly reflect the replacement part numbers for the different A15 RF board assemblies. Because of this, the majority of these assemblies are being replaced by kits that are only intended for use in very early versions of the 8560E Series instruments. These kits include parts that are not required for the 8560EC Series instruments, along with installation instructions that do not pertain to them.

While these kits, which are not intended for use with these instrument, do require that PartsID be consulted before ordering them, and they will then recommend the correct replacement parts, this note is meant to further relay this information.

Solution/Action:

When a replacement A15 RF assembly is required to repair any 8560EC Series instrument order one of the following, according to the options installed:

Part Number	Description
08563-60182	A15 RF Board – Option 008
08563-60184	A15 RF Board – Option 103
08563-60184	A15 RF Board – Option 103 & 008
08563-60185	A15 RF Board – Standard

The part numbers in the table above were current as of the publication of this service note. Refer to www.parts.agilent.com for up to date availability.

DO NOT order the 5063-0670, 5063-0671, or 5063-0672 kits to replace the A15 RF assembly in any 8560EC Series spectrum analyzer.