

8561B-11

S E R V I C E N O T E

SUPERSEDES None

HP 8561B Portable Spectrum Analyzer

Serials: 0000A00000/2925A00219

Duplicate Service Notes: 8560A-11

Modifying instruments for use with preselected external mixers

To be Performed by: HP Qualified Personnel, Customer

Parts Required:

Quan.	HP Part Number	Description
2	0698-8958	Resistor, MF 500K
1	5062-7714	RAM Expansion Kit
1	Latest Firmware Upgrade Kit (Call HP)	

Situation:

Earlier HP 8560A and HP 8561B Portable Spectrum Analyzers will not support HP 11974 series Preselected Millimeter Mixers.

Continued

DATE: 1 June 1991

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
GPB	5300	

© 1991 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.



Solution/Action

Instruments in the serial ranges listed above and contain their original A2 Controller assembly, HP part number 08560-60013, can be retrofitted to work with Preselected External Mixers by installing the kits and parts listed above. The Firmware and RAM Expansion kits are installed on the A2 assembly. The resistors replace A14R166 and A14R167 on the A14 Frequency Control assembly.