

8561B-15

S E R V I C E N O T E

SUPERSEDES: None

HP 8561B Portable Spectrum Analyzer

Serial Numbers: 0000A00000 / 9999A99999

Duplicate Service Notes:

8560A-12
8561A-26
8562A-57
8562B-55
8563A-08

Log Fidelity Spec Corrections

To Be Performed By: HP-Qualified Personnel or Customer

Situation:

Installation and Verification manuals for these spectrum analyzers contained information for testing and recording Incremental Log Fidelity in the Log Fidelity tests. This inclusion was an error.

In addition, earlier Installation and Verification manuals did not restrict the Log Fidelity in 10dB/Division to the top nine divisions of the display.

Solution/Action:

In the Log Fidelity test, ignore all references to Incremental Log Fidelity in the procedure, tables and test record. This applies to all log scales.

Add a note in Table 1-1 that the Log Fidelity in 10dB/Division applies only to the top nine divisions of the display.

DATE: 20 February 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
GPB	5300	

© 1993 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.

