

85629A-09

S E R V I C E N O T E

SUPERSEDES: None

HP 85629A Test and Adjustment Module

Serials Numbers: 0000A00000/9999A99999

Duplicate Service Notes: 85629B-07

Considerations for performing external mixer amplitude adjustment

To Be Performed By: HP-Qualified Personnel or Customer

Parts Required: None

Situation:

The External Mixer Amplitude Adjustment will fail or give incorrect results if the AVERAGE CNV LOSS and the CNV LOSS VS FREQ data are not set to the factory preset value of 30dB.

Solution/Action:

Before making the TAM External Mixer Amplitude Adjustment, make sure that the data for AVERAGE CNV LOSS and CNV LOSS VS FREQ are set to 30dB.

DATE: 06 February 1992

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
GPB	5300	

© 1992 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.

