

S E R V I C E N O T E

SUPERSEDES: None

8562A Portable Spectrum Analyzer

Serial Numbers: 0000A00000 / 9999A99999

Correct part number for A9 Input Attenuator

Duplicate Service Notes:

8562A-65

8562B-63

To Be Performed By: Agilent-Qualified Personnel or Customer

Situation:

The original service manual for the 8562A and 8562B Portable Spectrum Analyzers, part number 08562-90009, contained an incorrect part number for the A9 Input Attenuator. The part number was called out as 5086-7365, which has been replaced by a replacement kit 5062-6418. Neither of these will work in the 8562A or 8562B.

Solution/Action:

The correct A9 Input Attenuator part number for the 8562A and 8562B (non-option 026) is 5086-7783. Order 5086-6783 if a rebuilt attenuator is desired. The part number for the current service manual for these products is 08562-90123, and the CLIP part number is 08562-90124.

DATE: 05 November 1992

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
GPB	5300	