

S E R V I C E N O T E

SUPERSEDES: None

8563A Portable Spectrum Analyzer

Serial Numbers: 3146A00562 / 3337A02701

Duplicate Service Notes:

8560A-28

8560E-06

8561E-05

8562A-68

8563A-22

8563A-68

Improving focus reliability**Situation:**

Using diodes with a higher breakdown voltage will improve focus reliability.

Solution/Action:

Replace A17CR10 and A17CR30 with part number 1901-1413.

DATE: 13 December 1993

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
MODIFICATION AVAILABLE		
ACTION CATEGORY:	AGREEABLE TIME	<input type="checkbox"/> PERFORMANCE ENHANCEMENT <input checked="" type="checkbox"/> SERVICE/RELIABILITY ENHANCEMENT
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	AVAILABLE UNTIL: Life of product
AUTHOR: GPB	ENTITY: 5320	ADDITIONAL INFORMATION: