# S E R V I C E N O T E

SUPERSEDES: None

# **85644A Microwave Tracking Source**

Serial Numbers: 0000A00000 / 9999A99999

## **Duplicate Service Notes:**

85644A-01 85645A-01

## Firmware Upgrade Kit

To Be Performed By: Agilent-Qualified Personnel or Customer

#### Parts Required:

ROM Upgrade Kit, part number 85645-60020

#### **Situation:**

Later versions of instrument firmware sometimes are implemented to improve instrument performance and reliability.

#### **Solution/Action:**

A firmware upgrade kit has been set up for 85644A and 85645A Microwave Tracking Sources. The kit contains the latest revision instrument firmware and the applicable installation note. Table 1 lists the contents of the kit.

Continued

**DATE: 24 August 1992** 

#### ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
MODIFICATION AVAILABLE			
ACTION CATEGORY:	AGREEABLE TIME	■ PERFORMANCE ENHANCEMENT □ SERVICE/RELIABILITY ENHANCEMENT	
LOCATION CATEGORY:	■ CUSTOMER INSTALLABLE □ ON-SITE ■ SERVICE CENTER	AVAILABLE UNTIL: Support Life	
AUTHOR: GPB	ENTITY: 5300	ADDITIONAL INFORMATION:	

© 1992 AGILENT TECHNOLOGIES PRINTED IN U.S.A.



Table 1: ROM Upgrade Kit, Part Number 85645-60020

Part No.	Description	Qty.
85645-80004	UVEPROM, Programmed A3U18	1
85645-80005	UVEPROM, Programmed A3U78	1
85645-90024	Installation Note	1