

S E R V I C E N O T E

SUPERSEDES: None

8564E Portable Spectrum Analyzer

Serial Numbers: 0000A00000 / 3337A00118
with exceptions 3337A00105, 106, 109, 112, 115

Duplicate Service Notes:

8564E-03

8565E-03

5V Power Supply may current limit at turn-on**To Be Performed By:** Agilent-Qualified Personnel, Customer**Situation:**

At power-up, the 5-volt supply may current limit and cause the supply to remain at 3 volts. The problem is due two resistor values on the A6A2 daughter board.

Solution/Action:

Replace the A6A2 daughter board, part number 08564-60009. All boards in stock will have the correct resistor values.

DATE: October 1994

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
MODIFICATION RECOMMENDED					
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 0.5 Hour		
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: October 1996			
AUTHOR: GPB	ENTITY: 5300	ADDITIONAL INFORMATION:			