

## S E R V I C E N O T E

SUPERSEDES: None

**8565E Portable Spectrum Analyzer**

**Serial Numbers:** 0000A00000 / 3337A00146  
with exceptions 3337A00101, 103, 105, 116,  
108, 123, 129, 131, 133, 136, 137, 141.

**Duplicate Service Notes:**

8564E-03

8565E-03

**5V Power Supply may current limit at turn-on****To Be Performed By:** Agilent-Qualified Personnel, Customer**Situation:**

At power-up, the 5-volt supply may current limit and cause the supply to remain at 3 volts. the problem is due to resistor values on the A6A2 daughter board.

**Solution/Action:**

Replace the A6A2 daughter board, part number 08564-60009. All boards in stock will have the correct resistor values.

DATE: October 1994

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:					
<b>MODIFICATION RECOMMENDED</b>					
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input type="checkbox"/> ON SPECIFIED FAILURE <input checked="" type="checkbox"/> AGREEABLE TIME	STANDARDS:	Labor 0.5 Hour		
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT	USED PARTS:	<input type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input checked="" type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE		AGILENT RESPONSIBLE UNTIL: October 1996		
AUTHOR: GPB	ENTITY: 5300	ADDITIONAL INFORMATION:			