# **Installation Note**

Agilent Technologies ESA-L Series Spectrum Analyzers Color Display (Option 049) Retrofit Kit



Part Number E4403-90039 Supersedes: none Printed in USA September 2003



E4403-90039

#### Notice.

The information contained in this document is subject to change without notice.

Agilent Technologies makes no warranty of any kind with regard to this material, including but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Agilent Technologies shall not be liable for errors contained herein or for incidental or consequential damages in connection with the furnishing, performance, or use of this material.

## Color Display (Option 049)

Products Affected:	ESA E4403B ESA E4408B ESA E4411B	
Serial Numbers:	US0000000/US99999999	
Options:	049	
To Be Performed By:	(X) Agilent Service Center	
	(X) Personnel Qualified by Agilent	
	(X) Customer	
Estimated Installation Time:	0.25 Hours	

#### Introduction

This kit contains the parts and instructions to install the Option 049. No tools are required.

#### **Installation Kit Parts List**

Item	Description	Item Number
1	Color Display Installation Note	this note
2	Option Upgrade Entitlement Certificate	

### Procedure

**CAUTION** Electrostatic discharge (ESD) can damage or destroy electronic components. All work on electronic assemblies should be performed at a static-safe workstation. Refer to the documentation that pertains to your instrument for information about static-safe workstations and ordering static-safe accessories.

#### **Firmware Revision Verification**

- 1. Turn on the analyzer and wait for the power-on alignments to complete. Check that there are no error messages displayed.
- 2. Press **System**, **More**, **Show System**. Make a note of the firmware revision and see if Option B72, Expansion Memory, is listed on the display.
- 3. If the firmware revision is A.11.00 or later, the firmware does not need to be upgraded and you can skip steps 4 through 6.
- 4. If your firmware revision is prior to A.11.00, you must upgrade your analyzer firmware before the license key can be activated.
- 5. If Option B72, Expansion Memory *is* installed, you should upgrade the instrument firmware to the latest version using one of the following methods:
  - Download the instrument firmware via the world-wide web at http://www.agilent.com/find/esa\_firmware. This entire process of upgrading firmware will take approximately 45 minutes.
  - Receive the latest firmware upgrade disk set by ordering upgrade Option UE2.

**Note:** Special instructions in the Agilent ordering configurator should have made you aware of Option UE2 in case access to the internet wasn't available.

6. If Option B72, Expansion Memory is *not* installed, you must order upgrade Option B72, which includes the expansion memory and the latest ESA firmware upgrade disk set.

#### **Obtaining a License Key and Activating the Option**

The entitlement certificate supplied in this kit allows you to obtain a license key from our Agilent website so you can enable this upgrade option. Once you have retrieved the license key, you can begin the process of activating the option.

- 1. Press System, More, More, Licensing, Option. When you press Option, the alpha editor will be activated. For instructions on using the alpha editor, refer to the *Agilent Technologies* ESA Spectrum Analyzers User's Guide.
- 2. Use the alpha editor to enter the three-character designation for the option, in this case, "049", that you want to activate.
- 3. Press Enter when done.
- 4. Press License Key. When you press License Key the alpha editor will be activated.
- 5. Use the alpha editor and the numeric keypad to enter the 12-character license key number (for example: D7C374DABD5B) for the option that you want to activate.
- 6. Press **Enter** when done.
- 7. Press Activate to turn on the option.
- 8. If the option and license key entries were correct, a message stating "Option Activated" will appear on the analyzer display.

#### **Functional Testing**

- 1. Press System, More, Show System to verify existence of Option 1DR.
- 2. Press **Preset**, then press **Factory Preset**, if displayed. Verify that the trace is now yellow in color.