MFORMATION ONLY-DOES NOT COMMUNICATE A MODIFICATION OR SAFETY CONDITION

E4445A-09

S E R V I C E N O T E

Supersedes: None

PSA Series Spectrum Analyzer E4440A, E4443A, E4445A, E4446A, E4448A

Serial Numbers: [0000A00000 / 9999Z99999]

Please run the Frequency Response Adjustment (All Bands) after replacing the A10 Third Converter Assembly.

Danta	Dag		. J.
Parts	Req	uir	ea:

P/N Description Qty.

NONE

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: BNN PRODUCT LINE: 12

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2004 PRINTED IN U.S.A.

Agilent Technologies

April 13, 2004

Page 2 of 2 E4445A-09

Situation:

The PSA may fail frequency the frequency response test after replacing the A10 Third Converter assembly.

Solution/Action:

Please run the Frequency Response Adjustment(All Bands) after replacing the A10 third converter.