

11805B-01

11805B Transceiver Test Software  
Serial Numbers: 0000A00000 / 9999Z99999

Y2K update information.  
HP 11805B itself is Y2K compliant, as it does no Date Processing.  
If platform OS, and the hardware returns the correct date and year data,  
11805B works correctly. If a date related error occurs, the malfunction  
is caused by Operating System which is not Y2K compliant

To Be Performed By: Customer

Situation:  
Incorrect TEST start date and time

Solution / Action:

Product is obsolete.

If you wish to make the 11805B Y2K compliant, contact Test and Measurement  
Systems (TAMS) Inc. web page @ [www.tamsinc.com](http://www.tamsinc.com) for information on  
A Y2K upgrade.

Date: 16 October 1998

```
*****  
*                                                                 *  
*              INFORMATION ONLY                                *  
*              -----                                         *  
*  AUTHOR/ENTITY: _____JRR/1000_____                    *  
*  ADDITIONAL INFO: _____                               *  
*                                                                 *  
*****
```

Copyright Hewlett-Packard Company 1998