

8922B-02

HP8922B GSM BS Test Set

Serial Numbers:

0000A00000 / 9999Z99999

Y2K update information.

Product is not Y2K compliant to HP standards. Product is not being made compliant. Replacement is HP8922M. See situation below.

Parts Required:

HP P/N	Description
Replaced by HP8922M	GSM MS Test Set

Situation:

Y2K investigation has identified that the response from the BASIC function TIMEDATE is defective. This defect exists now and a TIMEDATE call would fail now if called in any BASIC application. Detection of this bug has caused all 8922 instruments below firmware B.07.07 to be classified as Y2K non-compliant. This bug has not been reported by customers which implies that it has not used in any applications to date.

Failure to install the Y2K upgrade will not cause the HP8922B to return an incorrect date/time stamp on 1st January 2000.

Solution / Action:

The 8922B is replaced by the 8922M with firmware B.07.07 or above which is Y2K compliant to HP standards. This firmware fixes the TIMEDATE bug but does not affect any other date-related processes within the instrument.

The 8922B will return the correct date/time stamp on 1st January 2000, without modification. It is recommended that no upgrade is required.

Date: 26 August 1998

```

*****
*
*                               INFORMATION ONLY
*                               -----
*
*   AUTHOR/ENTITY: AS/E600
*   ADDITIONAL INFO:
*
*****

```