

## S E R V I C E N O T E

SUPERSEDES: None

**Agilent 8922 GSM Test Sets**

Serial Numbers: See Below

**New kits for Audio Boards 1 and 2 (08922-60171 and 08920-60212)****Duplicate Service Notes:**

8922A-04	Serial Numbers: 0000A00000/9999Z99999
8922B-04	Serial Numbers: 0000A00000/9999Z99999
8922E-04	Serial Numbers: 0000A00000/9999Z99999
8922F-04	Serial Numbers: 0000A00000/9999Z99999
8922G-04	Serial Numbers: 0000A00000/9999Z99999
8922H-04	Serial Numbers: 0000A00000/9999Z99999
8922M-11	Serial Numbers: 0000A00000/9999Z99999
8922S-06	Serial Numbers: 0000A00000/9999Z99999
8922P-08	Serial Numbers: 0000A00000/9999Z99999
8922R-05	Serial Numbers: 0000A00000/9999Z99999
8922X-08	Serial Numbers: 0000A00000/9999Z99999

**Situation:**

Part number 08920-60212 (Audio Board) used on several Agilent products has been modified. This modified version is not suitable for use in the Agilent 8922 series of GSM Test Sets. For replacement purposes, use kit part number 08922-61907 which contains an unmodified version of the 8922 series Audio 2 board (Assembly A2).

In addition, a new kit (part number 08922-61908) has been created for the 8922 Audio 1 board (Assembly A3, part number 08922-60171) - order this kit when replacing the 8922 series Audio 1 board.

DATE: December 2000

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**AUTHOR:  
FHENTITY:  
E500

ADDITIONAL INFORMATION:

