

## S E R V I C E N O T E

SUPERSEDES: None

**8922 Family GSM MS Test Set  
A18 Spectrum Analyser Kit 08922-61845**

Serial Numbers: see below

**Due to a shortage of parts the 08922-61845 will no longer be used as the replacement kit for the A18 S/A.**

**Duplicate Service Notes:**

8922A-04 Serial Numbers: 0000A00000/9999Z99999  
 8922B-04 Serial Numbers: 0000A00000/9999Z99999  
 8922E-04 Serial Numbers: 0000A00000/9999Z99999  
 8922F-04 Serial Numbers: 0000A00000/9999Z99999  
 8922G-04 Serial Numbers: 0000A00000/9999Z99999  
 8922H-04 Serial Numbers: 0000A00000/9999Z99999  
 8922M-13 Serial Numbers: 0000A00000/9999Z99999  
 8922S-06 Serial Numbers: 0000A00000/9999Z99999  
 8922P-08 Serial Numbers: 0000A00000/9999Z99999  
 8922R-05 Serial Numbers: 0000A00000/9999Z99999  
 8922X-08 Serial Numbers: 0000A00000/9999Z99999

**Situation:**

The 8922 Family has now been discontinued. The A18 Spectrum Analyzer replacement kit will not be supported using the 08922-61845 replacement kit due to a shortage of parts. The replacement kit will now be a refurbishment S/A kit 08922-69845.

DATE: November 2001

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

**INFORMATION ONLY**

AUTHOR:

JKR

ENTITY:

E600

ADDITIONAL INFORMATION:

