

S E R V I C E N O T E

SUPERSEDES: None

**8922 Family GSM MS Test Set  
A18 Spectrum Analyser Kit 08922-61845**

**Serial Numbers:** see below

**Due to a shortage of parts the 08922-61845 will no longer be used as the replacement kit for the A18 S/A.**

**Duplicate Service Notes:**

- 8922A-04 Serial Numbers: 0000A00000/9999Z99999
- 8922B-04 Serial Numbers: 0000A00000/9999Z99999
- 8922E-04 Serial Numbers: 0000A00000/9999Z99999
- 8922F-04 Serial Numbers: 0000A00000/9999Z99999
- 8922G-04 Serial Numbers: 0000A00000/9999Z99999
- 8922H-04 Serial Numbers: 0000A00000/9999Z99999
- 8922M-13 Serial Numbers: 0000A00000/9999Z99999
- 8922S-06 Serial Numbers: 0000A00000/9999Z99999
- 8922P-08 Serial Numbers: 0000A00000/9999Z99999
- 8922R-05 Serial Numbers: 0000A00000/9999Z99999
- 8922X-08 Serial Numbers: 0000A00000/9999Z99999

**Situation:**

The 8922 Family has now been discontinued. The A18 Spectrum Analyzer replacement kit will not be supported using the 08922-61845 replacement kit due to a shortage of parts. The replacement kit will now be a refurbishment S/A kit 08922-69845.

DATE: November 2001

ADMINISTRATIVE INFORMATION

|                              |         |                         |
|------------------------------|---------|-------------------------|
| SERVICE NOTE CLASSIFICATION: |         |                         |
| <b>INFORMATION ONLY</b>      |         |                         |
| AUTHOR:                      | ENTITY: | ADDITIONAL INFORMATION: |
| JKR                          | E600    |                         |

