

S E R V I C E N O T E

SUPERSEDES: None

E7580A ProBER 2Mb/s Handheld Test Set

Serial Numbers: 0000U00000 / 9999U99999

Equipment no longer manufactured

Situation

Some equipment which is listed in the E7580A Service Manual is no longer manufactured. Engineers may have difficulty obtaining some of the listed equipment.

Equipment 37717C A3K can be replaced by 37718C Option 012, 200.

The 75 ohm stud HP 15522-80010 can be replaced by a feedthru 11094B.

DATE: April 2000

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:
GS

ENTITY:
E610

ADDITIONAL INFORMATION:

