

S E R V I C E N O T E

SUPERSEDES: NONE

**E7580A ProBER 2Mb/s Handheld Test Set**

**Serial Numbers:** GB00001300 / GB99999999

**Parts Required:**

Battery Charger E7580-69104

**Faulty Battery may be caused by faulty Battery Charger**

**Situation**

Some battery chargers sent out with instruments between the above serial number range, may have a connector which does not make a good connection with the main body of the instrument. These can be identified by a RED mark on the plug connector, and results in a flashing green light being shown at the DC in indicator LED, when the plug connector is lightly shaken.

**Action**

If you see an intermittent connection with this type of charger, please replace the battery charger under part number E7580-69104 and return the old charger for credit.

DATE: August 2000

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:			
<b>MODIFICATION RECOMMENDED</b>			
ACTION CATEGORY:	<input type="checkbox"/> IMMEDIATELY <input checked="" type="checkbox"/> ON SPECIFIED FAILURE <input type="checkbox"/> AGREEABLE TIME	STANDARDS:	LABOR 0.5 Hours
LOCATION CATEGORY:	<input checked="" type="checkbox"/> CUSTOMER INSTALLABLE <input type="checkbox"/> ON-SITE <input checked="" type="checkbox"/> SERVICE CENTER	SERVICE INVENTORY:	<input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
		USED PARTS:	<input checked="" type="checkbox"/> RETURN <input type="checkbox"/> SCRAP <input type="checkbox"/> SEE TEXT
AVAILABILITY:	PRODUCT'S SUPPORT LIFE	AGILENT RESPONSIBLE UNTIL: August 2002	
AUTHOR: GS	ENTITY: E610	ADDITIONAL INFORMATION:	

