

INFORMATION ONLY – DOES NOT COMMUNICATE  
A MODIFICATION OR SAFETY CONDITION

**E7903A-02**

**S E R V I C E N O T E**

---

Supersedes:  
None

**E7903A RouterTester P192/1 1550 nm Test Module**

**Serial Numbers:** [0000A00000 / 9999Z99999]

**If the monitor PCA on the power supply fails, then the complete power supply needs to be replaced with an exchnage assembly. This is a change from the previous support process where the monitor PCA or Power Supply could be changed individually**

**Parts Required:**

**E5202-69033 Exchange E5202-64033 PSU**

**Parts Obsolete:**

**E5202-69031 Exchange E5202-64031 Monitor PCA**

**E5202-69800 Exchange E5202-64800 PSU**

c

**ADMINISTRATIVE INFORMATION**

SERVICE NOTE CLASSIFICATION: <b>INFORMATION ONLY</b>
AUTHOR: DGH PRODUCT LINE: 2M
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002  
PRINTED IN U.S.A.



November 12, 2002