

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

E7916A-02

S E R V I C E N O T E

Supersedes:
None

E7916A RouterTester 10/1 VSR 850 nm Test Module

Serial Numbers: [0000A00000 / 9999Z99999]

If the monitor PCA on the power supply fails, then the complete power supply needs to be replaced with an exchange assembly. This is a change from the previous support process where the monitor PCA or Power Supply could be changed individually

Parts Required:

E5202-69033 Exchange E5202-64033 PSU

Parts Obsolete:

E5202-69031 Exchange E5202-64031 Monitor PCA

E5202-69800 Exchange E5202-64800 PSU

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR: DGH PRODUCT LINE: 2M

ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002
PRINTED IN U.S.A.



November 12, 2002