

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

SN J1981B-03

S E R V I C E N O T E

Supersedes:
NONE

J1981B VQT Tester

Serial Numbers: [0000A00000 / 9999Z99999]

The OEM vendor (Dolch) no longer supports the 20 Gbyte hard drive. In order to use the replacement 40 Gbyte HD the jumpers on the rear of the HD must be changed.

Parts Required:

P/N	Description	Qty.
None		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY
AUTHOR: DM PRODUCT LINE: 2J
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2002
PRINTED IN U.S.A.



November 5, 2002

Situation:

In order to use the replacement 40 Gbyte HD the jumpers on the drive must be set to 4092 Cylinder Limit.(see picture) Also BIOS may require updating.

Solution/Action:

