

INFORMATION ONLY – DOES NOT COMMUNICATE
A MODIFICATION OR SAFETY CONDITION

SN J1981B-04

S E R V I C E N O T E

Supersedes:
NONE

J1981B, VQT Portable Analyzer

Serial Numbers: SG44XXXXXX

A change was made to the J1981B platform requiring a new part number list to accommodate the changes made by the OEM.

Parts Required:

P/N	Description	Qty.
None		

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION: INFORMATION ONLY
AUTHOR: DM PRODUCT LINE: 2J
ADDITIONAL INFORMATION:

© AGILENT TECHNOLOGIES, INC. 2004
PRINTED IN U.S.A.



January 30, 2004

Situation:

All J1981B VQT units whose serial number begins with SG44 or included in the list below require the use of the new BOM for repair.

SG42180180	SG42210118	SG42220110
SG42180181	SG42210119	SG42220111
SG42180182	SG42210120	SG42220112
SG42180183	SG42210121	SG42220113
SG42180184		
SG42180185		

Solution/Action:

A copy of the BOM can be found at:

http://nstd.corporate.agilent.com/servicecenter/j1981b_+.htm