

S E R V I C E N O T E

SUPERSEDES: None

3065 Board Test System**New Vendor for 3065H Scanner Power Supplies****Situation:**

This is the second Service Note addressing the new power supplies for the 3065 systems. The first addressed the LH power supplies and was sent out by mistake as Service Note 3070-23, but correctly as 3065-80. This service note (3065-81) covers the kit used to replace the New Jersey Division power supplies in the 3065H systems.

Solution:

The NJD power supplies are no longer supported. A new vendor, Power-One, has been selected to replace the LH supplies previously structured in the kit. The old kit used to upgrade from NJD power supplies to LH power supplies, part number 03065-80035, has been revised to upgrade to Power-One supplies. It is available at SMO/SME. The new kit contains two replacement power supplies mounted on a supply tray and all the hardware, documentation and other materials necessary for the upgrade. If there are any problems with the NJD power subsystem, it should be replaced using this kit.

DATE: August 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
GS	0980	