

S E R V I C E N O T E

SUPERSEDES: None

**3065 Boardtest System**

Serial Numbers:0000A00000 / 9999Z99999

**3065 Vacuum Solenoid Valve Vendor Change**

To Be Performed By: HP-Qualified Personnel

**Situation:**

The original vendor for the 3065 vacuum solenoid valve was Skinner. However, Skinner has discontinued the solenoid valve p/n 0101-0588.

**Solution/Action:**

There has been a vendor change for the vacuum solenoid valve p/n 0101-0588 used on the Internal Vacuum Control Module. Parker Hannifin valve was chosen as the replacement for Skinner valve, and the new part number is 03065-88703. The Skinner repair kit 03065-88700 has also been obsoleted, and the Parker Hannifin repair kit 03065-88704 will be set up.

Customers with Skinner valves will need to replace them with Parker Hannifin valves since 0101-0588 and 03065-88700 will not be orderable anymore.

DATE: September 1997

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
<b>INFORMATION ONLY</b>		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
JL	0980	

