

S E R V I C E N O T E

SUPERSEDES:3065-83

Model Number 3065 Board Test System**New 3065 Vacuum Valve and Valve Replacement Kit****Situation:**

The 3065 vacuum valve and vacuum valve replacement kit have been discontinued by the vendor. It will no longer be possible to repair the older vacuum valve.

Solution:

If there are problems with an 3065 vacuum valve, it will be necessary to replace it. The new vacuum valve kit, part number 03065-68702 (this part number has been corrected from previous service note 3065-83), consists of the vacuum valve (03065-88703) and a new piece of sheet metal, (11347-01202). The new sheet metal conforms to the form factor of the new valve. There is also a new vacuum valve replacement kit, part number 03065-88704. It will be used to repair the new valve.

The old part numbers, 0101-0588 and 03065-88700, have been discontinued. If you order either of the old part numbers, you will be asked to order the new vacuum valve kit instead. Please note that the new repair kit cannot be used on the old vacuum valve. This means that all customers with vacuum valve problems will have to purchase a new vacuum valve. Since we are no longer able to repair the old valves, this is the only option.

DATE: September 1998

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
HDR	0980	None