

S E R V I C E N O T E

SUPERSEDES: None

3070 Board Test System**New Vendor for 3065 Scanner Power Supplies****Situation/Solution:**

The LH power supplies for the 3065 are no longer being manufactured. A new vendor, Power-One, has been selected. A new kit, part number 03065-66205, has been set up at SMO/SME. The new kit contains two replacement power supplies mounted on a supply tray and all the hardware and documentation necessary to connect the new supplies. The existing power supplies, 0950-1824 and 0950-1781, will continue to be refurbished and will be available as exchange parts for customers as long as possible. If not available, the new supply will be substituted, and will replace both power supplies.

The 3065H, the first 3065 model, had power supplies from Agilent's New Jersey Division. The replacement kit, 03065-80035, went from the NJD power supplies to the LH power supplies. It is being revised for the Power-One supplies and will be available in June.

DATE: August 1996

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:

GS

ENTITY:

0980

ADDITIONAL INFORMATION:

