

S E R V I C E N O T E

SUPERSEDES: None

HP 3070 Board Test System**New MPUs will be shipping****Situation:**

The E4000-66202 MPU has been replaced with a new MPU which incorporates the latest technology. It provides power factor correction and will be completely backward compatible with the current MPU. There is no need to replace a working MPU.

Solution:

The new MPU will start shipping in new Board Test systems in late January, 1998. The new part number is E4000-66203. The new exchange part number is E4000-69203. The older MPUs in the Blue Stripe pipeline will continue to be used until the pipeline is empty. The Series I exchange MPUs will also be updated when that pipeline is empty. The old Series I part number is E4000-69212; the new Series I part number is E4000-69213.

DATE: July 1998

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

INFORMATION ONLY

AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
GS	0980	

© 1998 HEWLETT-PACKARD COMPANY
PRINTED IN U.S.A.

