

S E R V I C E N O T E

SUPERSEDES: 3070-38

3070 Board Test System

Fan Replacement Kit for 3070 Series II Systems

Situation:

Service note 3070-38 provided a fan conversion for Series II systems using the Series 3 cooling design. Although this design met all known regulations, many customers found that this design produced an objectional level of noise, particularly those covered by the European Machine Directive.

Series II systems that were converted to Series 3 cooling produce the same level of noise as the Series 3 systems. As a result of complaints about this noise the Manufacturing Test Division has discontinued the Series II conversion program, canceled service note 3070-38 and withdrawn the material kits for this conversion.

Customers who experience problems with wear and contact problems with MINT pins should use the procedure and recommendations in Service note 3070-37.

Solution / Action:

There will be a future Service Note concerning a fan conversion kit which lowers fan noise and improves cooling. The new solution will be available for purchase approximately 12/1/99

DATE: July 1999

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
INFORMATION ONLY		
AUTHOR:	ENTITY:	ADDITIONAL INFORMATION:
TT	0980	