

S E R V I C E N O T E

SUPERSEDES: None

**Agilent 3070 Board Test System**

**Serial Numbers:** 0000A00000 / 9999Z99999 (All 3070 Pay-per-use systems)

**To Be Performed By:** Agilent Technologies Qualified Personnel

**Parts Required:**

0960-2134	Button Adapter
E9970-63200	RJ-45 to DB-9 Adapter

Pay-Per-Use Button Adapter and RJ-45 to DB-25 Adapter have been replaced

**Situation:**

The Pay-Per-Use Button Adapter (P/N 0960-0890) and RJ-45 to DB-25 Adapter (P/N E4000-62106) have been replaced. New Pay-Per-Use systems as well as new SCSI to RS-232 MUX box kits (P/N E3788A) now use the RJ-45 to DB-9 adapter (P/N E9970-63200). The RJ-45 to DB-25 adapter (P/N E4000-62106) is still an orderable part and will continue to be available through ATLS.

Replacement parts will be available in mid-July:

- The Pay-Per-Use Button Adapter has been replaced with a new Button Adapter, P/N 0960-2134.
- The RJ45-to-DB25 Adapter has been replaced with a RJ-45 to DB-9 Adapter, P/N E9970-63200.

*Continued*

DATE: July 2000

ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:		
<b>INFORMATION ONLY</b>		
AUTHOR: CE	ENTITY: 0980	ADDITIONAL INFORMATION:



**Note**

The new Pay-Per-Use adapters are NOT compatible with 725/50 controllers. Telecom Pay-Per-Use systems will not be compatible until the B.03.80 software release.

**Solution / Action:****NOTE**

There is no need to order either replacement part unless an existing part fails in the field.

If a Pay-Per-Use system malfunctions because of a failure of either the Button Adapter or the RJ-45 to DB-25 Adapter then both parts must be replaced with their new counterparts.

In order to use the new adapters, Pay-Per-Use systems must run B.03.64 or newer software. The B.03.64 software patch is compatible with both the old style adapters and the replacement adapters.

Please return working old style Pay-Per-Use adapters (used or unused) to:

Helene Harrison  
Agilent Technologies, Inc.  
815 14th Street SW,  
MS AM113  
Loveland, CO 80537

The adapters that are returned will be used as support parts for both the Pay-Per-Use systems that use 725/50 controllers and the Telecom Pay-Per-Use systems that require button adapter replacements. They will also be used for new Telecom Pay-Per-Use systems until the Telecom software release, B.03.80, is available.

The B.03.64 software patch will be released in early July; B.03.80 is currently scheduled for this fall.