

## S E R V I C E N O T E

SUPERSEDES: 5DX-97-01  
Dated January 17, 1997

## HP 5DX Structural Process Test System

### Latest CPU cards do not have com2

**Situation:**

The latest version of the CPU cards do not have the com2 port installed on the card backplane.

**Solution:**

For systems that are currently being shipped, the com2 port for the master cpu and the server cpu's are installed on the computer assembly backplane. The master com2 port is located next to J05026 in the upper left corner of the computer assembly backplane. The server com2 port is located in the upper right hand corner of the backplane. For systems already installed, the com2 port must be installed. The com2 port connection is located on the cpu card and is identified as cn15 rs232 port2. The ribbon cable is included with cpu card.

DATE: September 1997

## ADMINISTRATIVE INFORMATION

SERVICE NOTE CLASSIFICATION:

### INFORMATION ONLY

AUTHOR:

KP

ENTITY:

0980

ADDITIONAL INFORMATION: