

---

This Release Note applies to the new code C32 of the ATM WAN 2 Module and the I/O cards code upgrade.

Level C32 fixes thruput problem with OC3/STM1 card on blade WAN2 (carrier 1.5).

Previous level did not permit to reach 155Mbps with OC3/STM1 Wan card, with C32 all types of Wan cards (E1/T1/E3/DS3/OC3/STM1) are now supported with no restriction.

This level is mandatory for OC3/STM1 I/O card and recommended for E1/T1E3/DS3.

The microcode upgrade for I/O card is only mandatory to be able to use the functions of the IBM 8265 (i.e Performance Monitoring).